

Session Program

2 June 2026

Workshop regarding CE marking

2nd Session

CUBE, Rausing

Tuesday 2 June

12:45

2nd Session

Session | Location: CUBE, Rausing

12:45–13:00 MAX IV guidelines regarding CE marking and motion

13:00–13:30 Risk assessment (ISO 12100)

13:30–14:00 Functional safety (ISO 13849)

14:00–14:30 Testing & technical file

14:30–15:00 Declaration & CE marking

15:00